Dated:

BUILDINGSAFETYCERTIFICATE

Certified that the existing building MONT FORT CHILDREN ACADEMY (name of thebuilding or
premises) at GOVERDHANPUR ROAD LAKSAR HARIDWAR UTTARAKHAND PIN CODE
247663(address)comprisedofbasement(s)and
(upperfloors)owned/occupiedby
(upperfloors)owned/occupiedby
(nameoftheInstitution)havecompliedwiththe
BuildingsafetyrequirementsinaccordancewithNationalBuildingcodeRules,andverifiedby the officers
concerned ofCD.P.W.D.Lake (Name of Department/ Govt.)
on2-1-231(date of inspection) in the presence of
Manager Mont fact Unilden Madername and addresses of the
Manager/Secretaryorhisrepresentative)andthatthebuilding/premisesisfitforoccupancy
uptoclasses(X/XII)witheffectfromforaperiodof
years in accordance with rule and subject to compliance of the specific
conditions as appended.
1. Fine time water
2. sepret sencan
1. Find him would take 2. Selprate structor 3. Emerge of the selprate enver 4. Selprate spreet enver Issuedon 3-1-2-1, at 12-1-2-1 by
4. Separt Strate
Issuedon3-1-2-3
*Strikeoutwhicheverisnotapplicable.
Signaturewith Seal: 153 01 2 9
Name: Anil Kermer
Designation: $\rho \cdot \varepsilon$
ivame&AddressofDepartment/Office: पुरुषक अभियन्ता
(AssistantEngineer&aboveofficerofconcernedGovt penfurtental) निर्दा
लक्सर

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

^{*} The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translatednotarizedversioninEnglishbeuploadedalongwiththeoriginalvernacularcertificate as a single pdf.